U.S. DEPARTMENT OF HOMELAND SECURITY FEDERAL EMERGENCY MANAGEMENT AGENCY

National Flood Insurance Program

FLOODPROOFING CERTIFICATE

FOR NON-RESIDENTIAL STRUCTURES

OMB No. 1660-0008

Expiration Date: July 31, 2015

The floodproofing of non-residential buildings may be permitted as an alternative to elevating to or above the Base Flood Elevation; however, a floodproofing design certification is required. This form is to be used for that certification. Floodproofing of a residential building does not alter a community's floodplain management elevation requirements or affect the insurance rating unless the community has been issued an exception by FEMA to allow floodproofed residential basements. The permitting of a floodproofed residential basement requires a separate certification specifying that the design complies with the local floodplain management ordinance.

BUILDING OWNER'S NAME MIDNIGHT CO	VE COMDOMINIUM	AGRIATINI			
STREET ADDRESS (Including Apt.	Unit, Suite, and/or Bldg. Number)	OR P.O. ROUTE AND BOX NUM	BER		
	HT COVE FOAT	>			
OTHER DESCRIPTION (Lot and Block Numbers, etc.) CLUSTIANS ADDITION					*
CITY SAFASOTA				STATE ZIF	3+242
	SECTION I - F	LOOD INSURANCE	RATE MAP (FIRM)	INFORMATION	1010
Provide the following from	n the proper FIRM:				
COMMUNITY NUMBER	PANEL NUMBER	SUFFIX	DATE OF FIRM INDEX	FIRM ZONE	BASE FLOOD ELEVATION
125144	0143	E	09/03/1992	AE	(In AO Zones, Use Depth)
Indicate elevation datum used I	for Base Flood Elevation shown a	above: NGVD 1929	NAVD 1988 Other/Source:		
SECTION	II – FLOODPROOFING	INFORMATION (B	y a Registered Profe	essional Engineer o	or Architect)
	Construction Drawings				
Floodproofing Design Elev					
Building is floodproofed to an el (Elevation datum used must be	levation of 12 . feet (le e the same as that used for the	Puerto Rico only: Base Flood Elevation.)	meters). NGVD 1929	□ NAVD 1988 □ Other/	Source:
	building above the lowest adjac		feet (In Puerto Rico only: _	meters).	
For Unnumbered A Zones					
Highest adjacent (finished) gra	ade next to the building (HAG) _	feet (In Pu	erto Rico only:	meters)	
	1988 Other/Source:			motors/	
	rposes, the building's floodprod	ofed design elevation must	be at least 1 foot above the B result in a higher premium.)	ase Flood Elevation to rece	ive rating credit. If the building
SI	ECTION III – CERTIFIC	CATION (By a Regi	stered Professional	Engineer or Archite	ect)
Non-Residential Floodproo					
I certify that, based upon are in accordance with acc	development and/or review of s cepted standards of practice fo	structural design, specificat or meeting the following pro	ions, and plans for constructions:	on, the design and methods	of construction
The structure, toge walls that are subs	ther with attendant utilities and tantially impermeable to the pa	l sanitary facilities, is water issage of water.	tight to the floodproofed desig	gn elevation indicated above	e, with
All structural comp debris impact force	onents are capable of resisting es.	hydrostatic and hydrodyna	mic flood forces, including the	effects of buoyancy, and a	inticipated
l certify that the information by fine or imprisonment un	on on this certificate represents ader 18 U.S. Code, Section 100	my best efforts to interpre 1.	t the d ata ava ilable. I understa	and that any false statemen	nt may be punishable
CERTIFIER'S NAME			NUMBER (or Affix Seal)		
MARK H. SY	MI 1H	FL	. REGISTRATION	1 NO! AROOD	9731
ARCHITECT OF	F RECORD		NITH ARCHITEC	The PA	
ADDRESS		CITY		STATE	ZIP CODE
	5 MIHORGA	SAR	ASOTA F	2000	34242
SIGNATURE WELL TO	him	DATE 291	and the second s	741.346.72	05 ×1
Copie	es should be made of this Cert	tificate for: 1) community	official, 2) Insurance agent/o	company, and 3) building o	owner.

Flood Emergency Operations Plan Midnight Cove Clubhouse Addition, 6302 Midnight Cove Road, Sarasota, Florida 34242

The Midnight Cove Association has clearly directed that the responsibility for flood-proofing the building by installing the flood barriers at all exterior doors rests with the Maintenance Supervisor.

Chain of Command:

Chair of Building - 1. In command of all flood-proofing and disaster procedures. Determines & Grounds Comm. when building should be flood-proofed and all employees should evacuate.

Maintenance Supervisor

- 1. If Chair of Building & Grounds is unavailable, absent, or unable to perform, will assume command of all flood-proofing and disaster preparation. 2. Direct staff to perform flood-proofing and disaster preparation.

Supervisor

Assistant to Main. - 1. If Maintenance Supervisor is unavailable, direct staff to perform floodproofing and disaster preparation.

Notification Procedures:

& Grounds Comm.

- Chair of Building 1. Upon notification by Sarasota County Emergency Management, local weather stations, or NOAA weather radio of a potential flood event/hurricane impact within 72 hours to Sarasota County and Siesta Key will notify Maintenance Supervisor to activate pre-determined employee phone tree or text/email message alert informing employees to come to the building and begin flood-proofing procedures.
 - 2. Notify Midnight Cove Association Board of Directors that the clubhouse addition is beginning flood-proofing procedures and when those procedures are complete and the building is flood-proofed.

Assigned Duties:

Maintenance Supervisor

- 1. Have flood barriers retrieved from storage and prepped for installation.
 - 2. Inventory all flood barrier fastening hardware.
 - 3. Within 48 hours of potential flood event/hurricane impact inspect floodproofing installation.
 - 4. Direct staff to clear all interior areas by windows, elevate electronics, clear all exterior loose furniture, trash cans, signage, etc. from around the property and store inside.
 - 5. Prior to evacuation, turn off all electricity at the panels and the water at the shut-off valve.
 - 6. Before 48 hours of potential flood event/hurricane impact, install flood barrier panels with staff and perform all flood-proofing procedures.

Supervisor

Assistant to Main. - 1. If Maintenance Supervisor is unavailable, perform flood-proofing and disaster preparation as listed above.

Evacuation Plan:

Chair of Building & Grounds Comm.

- 1. Within 48 hours of potential flood event/hurricane direct staff to evacuate.

Maintenance Supervisor

- 1. Ensure that all staff have evacuated the building and then Siesta Key either by the north or south bridge, whichever is deemed safer by local authorities. 2. Ensure that the building is secure.

Periodic Training/Exercise Program:

Maintenance Supervisor

- 1. On an annual basis, no later than May 1st of each year, organize floodproofing training/exercise program in coordination with Sarasota County **Emergency Management.**
 - 2. Direct staff as to their assigned duties and time the flood barrier installation to determine proper timing in a disaster situation.
 - 3. Practice installing flood barriers with staff.

Inspection and Maintenance Plan Midnight Cove Clubhouse Addition, 6302 Midnight Cove Road, Sarasota, Florida 34242

The Midnight Cove Association has clearly directed that the responsibility for the storage. inspection, and maintenance of the flood barriers and the integrity of the exterior flood-proofing of the building openings doors rests with the Maintenance Supervisor.

Mechanical Equipment:

Maintenance Supervisor

- 1. On an annual basis, no later than May 1st of each year, shall have the water supply line backflow preventer and the sanitary sewer line backwater valve inspected and repaired if necessary.

Supervisor

Assistant to Main. - 1. If Maintenance Supervisor is unavailable, direct staff to perform, shall have the water supply line backflow preventer and the sanitary sewer line backwater valve inspected and repaired if necessary.

Flood Barriers:

Maintenance Supervisor

- 1. On an annual basis, no later than May 1st of each year, shall have the flood barriers retrieved from storage to ensure they are properly labeled and to inspect the gaskets and seals to ensure they are in good working order. If damaged they will be repaired as necessary.
 - 2. Flood barrier closures will be inspected to ensure that the barriers will fit properly.
 - 3. Inventory all flood barrier fastening hardware. Replace missing or damaged parts.

Supervisor

Assistant to Main. - 1. If Maintenance Supervisor is unavailable, absent, or unable to perform, shall have the flood barriers retrieved from storage and inspected for damage and repaired as necessary and inventory all flood barrier fastening hardware.

Walls & Wall Penetrations:

Maintenance Supervisor

- 1. On an annual basis, no later than May 1st of each year, shall have the exterior walls and wall penetrations from 1 foot above BFE to grade inspected for cracks and potential cracks.

Supervisor

Assistant to Main. - 1. If Maintenance Supervisor is unavailable, absent, or unable to perform, shall have the exterior walls and wall penetrations inspected for cracks and potential cracks.

6302 Midnight Cove Flood Panel Installation



West Side - window sills above base flood elevation



NW Corner - window sills above base flood elevation



South Side - window sills above base flood elevation



Expansion joint between new floodproofed structure and existing structure

Photos taken December 29, 2014 by Mark H. Smith AIA, Architect of Record

marth

Signature

6302 Midnight Cove Flood Panel Installation



Front Door Flood Panel Installation



Front Dr Flood Panel Edge Connection



Rear Door Flood Panel Installation



Rear Dr Flood Panel Edge Connection

Record /

Signature